HO-1035 Ward-Mullinex Property 15959 Union Chapel Road, Daisy Public

DESCRIPTION:

The only surviving structure on the Ward-Mullinex Property is the stone "incinerator." It is a one-story, one-bay square rubble stone structure that is 11 feet, 4 inches wide, 8 feet, 7 inches deep, and 8 feet tall. The north and south walls are battered beginning 3 feet above the current ground level. The structure has been re-pointed with Portland cement. The west elevation has an opening at ground level that is now mostly below grade. Above this is a second opening with two machine-made pintels on the south jamb To the north of the top opening is scratched into the Portland cement, while it was wet, a date that has been interpreted as "1852", though the "8" is not closed and may actually be a backward "9". There are no openings on the north, south, or east elevations. The interior has bars and rods of iron or steel near the top that ran east-west, but most of them are now bent inward and down. They support a corbelled stone cap that is now partially collapsed. The east wall, at the top, has several courses of brick in the center that appear to have been for a chimney.

SIGNIFICANCE:

The Ward-Mullinex Property was sold in 1880 to Sarah Ward for just over \$200, indicating that there were no improvements to the property at that time. Ward and her husband, John, probably built a house at this location, but no buildings survive. Ward was a 40-year-old farmer. The Wards sold the property in 1900 to their 30-year-old son, George Ward, for \$1,500, indicating that there were improvements at that time. George most likely leased the house to his parents. Living with John and Sarah Ward was their daughter-in-law, Emma, and her two children. In 1899 Emma Ward was appointed school teacher for School No. 7 at Rover, in the Fourth District. In 1907 Emma Ward bought the Daisy house from her brother-in-law, and she continued to teach. She sold the property in 1929 to Norman and Pauline Mullinex, who owned and operated a store. The Mullinexes sold the property to Norman's brother, Robey, in 1944. Robey Mullinex operated an automobile dealership in Daisy. The only surviving structure on the site is the stone "incinerator."

Maryland Historical Trust Maryland Inventory of Historic Properties Form

historia.					
historic	Ward-Mullinex	Property			
other					
2. Location					
street and number	r 15959 Union C	hapel Road			_ not for publication
city, town	Daisy				vicinity
county	Howard				
3. Owner of	f Property	(give names and mailin	g addresses of all owners	:)	
name	Howard County	MD Dept. of Public Work	s		
street and numbe	r 3430 Courthous	se Drive		telephone	
city, town	Ellicott City		state MD	zip code	21043
city, town	Ellicott City	Howard County Courthouse tax map 13		THERESER WAS A	ID number
Cont Cont Dete Reco	tributing Resource is tributing Resource is tributing Resource is trimined Eligible for trimined Ineligible for orded by HABS/HA		and Register yland Register		
Cont Cont Dete Dete Reco	tributing Resource is tributing Resource is tributing Resource is trimined Eligible for trimined Ineligible for orded by HABS/HA	n National Register District n Local Historic District the National Register/Maryl r the National Register/Mar ER rt or Research Report at Mi	and Register yland Register		
Cont Cont Dete Dete Reco	tributing Resource is tributing Resource Indicate	n National Register District n Local Historic District the National Register/Maryl r the National Register/Mar ER rt or Research Report at Mi	and Register yland Register		

-	_		
1.	Des	crip	tion

Inventory No. HO-1035

Condition

excellent	X deteriorated	
good	ruins	
fair	altered	

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

SUMMARY:

The only surviving structure on the Ward-Mullinex Property is the stone "incinerator." It is a one-story, one-bay square rubble stone structure that is 11 feet, 4 inches wide, 8 feet, 7 inches deep, and 8 feet tall. The north and south walls are battered beginning 3 feet above the current ground level. The structure has been re-pointed with Portland cement. The west elevation has an opening at ground level that is now mostly below grade. Above this is a second opening with two machine-made pintels on the south jamb To the north of the top opening is scratched into the Portland cement, while it was wet, a date that has been interpreted as "1852", though the "8" is not closed and may actually be a backward "9". There are no openings on the north, south, or east elevations. The interior has bars and rods of iron or steel near the top that ran east-west, but most of them are now bent inward and down. They support a corbelled stone cap that is now partially collapsed. The east wall, at the top, has several courses of brick in the center that appear to have been for a chimney.

DESCRIPTION:

The Ward-Mullinex Property is located at 15959 Union Chapel Road, at the southeast corner of Union Chapel Road and Daisy Road, in Daisy in western Howard County, Maryland. The only surviving structure on the site is the stone "incinerator." It is located on the south end of the lot, near the east side of the lot, and faces west toward Daisy Road. There is a driveway from Daisy Road that passes between low stone walls and runs eastward toward the "incinerator." This is a one-story, one-bay square rubble stone structure that is 11 feet, 4 inches wide, 8 feet, 7 inches deep, and 8 feet tall. The north and south walls are battered beginning 3 feet above the current ground level. The structure has been re-pointed with Portland cement.

The west elevation has an opening at ground level that is now mostly below grade. There is a hinge pintel on the south jamb, near the top of the opening, and the lintel is steel angle that is mostly rusted away. Above this is a second opening with two machine-made pintels on the south jamb and a piece of angle steel coming out of the wall to the north of the north jamb. The interior of the opening has an angle iron lintel. There was an angle iron lintel on the exterior, but it is now gone; it has left an impression in the Portland cement re-pointing. To the north of the top opening is scratched into the Portland cement, while it was wet, a date that has been interpreted as "1852", though the "8" is not closed and may actually be a backward "9". There are no openings on the north, south, or east elevations.

The interior is square, rubble stone walls with bars and rods of iron or steel near the top that ran east-west, but most of them are now bent inward and down. They support a corbelled stone cap that is now

Inventory No. HO-1035

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 7 Page 1

partially collapsed. The east wall, at the top, has several courses of brick in the center that appear to have been for a chimney. The west wall, in the center has a shallow recess that could have been for a chimney. There is modern wire-cut brick debris with mortar on it, in the bottom of the interior. The east wall brick appears to be older. There is no clear evidence of earlier mortar visible. The bottom of the structure is filled with much debris, preventing any inspection of much of the interior.

8. Signification	ance			Inventory No. HO-1035
Period	Areas of Significance	Check and j	ustify below	
1600-1699 1700-1799 X 1800-1899 X 1900-1999 2000-	agriculture archeology X architecture art commerce communications community planning conservation	economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government religion science social history transportation other:
Specific dates	N/A		Architect/Builder N/A	
Construction da	ites N/A			
Evaluation for:				
	National Register		Maryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form - see manual.)

SUMMARY:

8 Significance

The Ward-Mullinex Property was sold in 1880 to Sarah Ward for just over \$200, indicating that there were no improvements to the property at that time. Ward and her husband, John, probably built a house at this location, but no buildings survive. Ward was a 40-year-old farmer. The Wards sold the property in 1900 to their 30-year-old son, George Ward, for \$1,500, indicating that there were improvements at that time. George most likely leased the house to his parents. Living with John and Sarah Ward was their daughter-in-law, Emma, and her two children. In 1899 Emma Ward was appointed school teacher for School No. 7 at Rover, in the Fourth District. In 1907 Emma Ward bought the Daisy house from her brother-in-law, and she continued to teach. She sold the property in 1929 to Norman and Pauline Mullinex, who owned and operated a store. The Mullinexes sold the property to Norman's brother, Robey, in 1944. Robey Mullinex operated an automobile dealership in Daisy. The only surviving structure on the site is the stone "incinerator."

SIGNIFICANCE:

The Ward-Mullinex Property at the southeast corner of Union Chapel Road and Daisy Road was part of the William H. Gaither Farm in the 1870s and was sold to Henrietta and Zadok Talbert in 1876. According to the 1878 Hopkins Atlas of Howard County, the Talberts were living well to the east of this site, and there is nothing indicated on this site. In 1880 the Talberts sold 5 acres to Sarah Ward for just over \$200, indicating that there were no improvements to the property at that time. Ward and her husband, John, probably built a house at this location, but no buildings survive. Ward was a 40-year-old farmer, and it is not known if he owned a farm, leased one, or worked as a hired hand on one. The Wards sold the property in 1900 to their 30-year-old son, George Ward, for \$1,500, indicating that there were improvements at that time. George was living with his wife and mother-in-law in Baltimore City,

Inventory No. HO-1035

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 8 Page 1

where he worked as a book keeper, and he most likely leased the house to his parents. Living with John and Sarah Ward was their daughter-in-law, Emma, and her two children. The Ward's youngest son, Thomas, was apparently deceased, and in 1899 Emma Ward was appointed school teacher for School No. 7 at Rover, in the Fourth District. In 1907 Emma Ward bought the Daisy house from her brother-in-law for \$1,250, and she continued to teach at least until 1910. She sold the property in 1929 to Norman and Pauline Mullinex, who owned and operated a store on the north side of Union Chapel Road. The Mullinexes sold the property to Norman's brother, Robey, in 1944. Robey Mullinex operated an automobile dealership in Daisy, and in 1966 the Ward Property became part of Mullinex Motors. Several CMU shop buildings were constructed on the site, and these have recently been demolished. The fate of any earlier buildings that the Wards built is unknown.

The only surviving structure on the site is the stone "incinerator." While it may have been used most recently as an incinerator, whether it was built for that purpose is problematic. There was a brick chimney on the structure, at the rear on top of the stone, with a door on the front and a clean-out below it. Only the hinge pintels of the door to the top opening survive. The lower opening is mostly buried, but there is a pintel near the top of this opening, so it must also have had a door. The structure has been built or heavily re-pointed with Portland cement in the twentieth century, which could mean either heavy use that deteriorated the structure, or a repurposing of the structure. Scratched into this Portland cement, while it was wet, is a date that has been interpreted as "1852", though the "8" is not closed and may actually be a backward "9". Most stone is not good in heat, so stone structures subjected to high heat (such as a lime kiln or iron furnace) were typically lined with brick. There is no evidence of any brick lining, though there may be below the rubble that has filled the interior of the structure. The form of the structure and the arrangement of its openings are not consistent with either a lime kiln or iron furnace. Archaeological investigations in and around it may be able to further inform us about the original use of the structure. This researcher has never seen an incinerator on a farm before. Typically, what little that was available (famers have never wasted much) that could be burnt, and was, was done so in a pile or, later in the 20th c., in a wire basket or metal drum. Going to the effort to build such a structure as this suggests a great deal of activity here, whatever it was being used for. A better understanding of what this was will take time and research.

¹ U. S. Bureau of the Census, District 4, Howard County, Maryland, 1880, 1900, 1910; Precinct 10, Baltimore City, Maryland, 1900. Howard County Board of School Commissioners, "Minutes", book 3, 1899-1917, frontispiece & p. 17. Hugh E. Flaherty, "A Short History of Daisy," typescript, 2008.

9. Major Bibliographical References

Inventory No. HO-1035

See footnotes

10. Geographical Data

Acreage of surveyed property
Acreage of historical setting
Quadrangle name

4.1894 A

5 A

Woodbine
Quadrangle scale: 1:24000

Verbal boundary description and justification

The boundaries consist of the outlines of the property, tax map 13, parcel 57, which encompasses all of the historic buildings and features on the site.

11. Form Prepared by

name/title	Ken Short		
organization	Howard County Department of Planning & Zoning	date	October 2011
street & number	3430 Courthouse Drive	telephone	410-313-4335
city or town	Ellicott City	state	MD

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust Maryland Department of Planning 100 Community Place Crownsville, MD 21032-2023 410-514-7600

THE WARD-MULLIN PROPERTY (HO-1035) 15959 UNION CHAPEL ROAD

CHAIN OF TITLE


GRANTOR/HOME	GRANTEE/HOME	DATE	LIBER/ FOLIO	INSTRU- MENT	CONSIDER- ATION	ACREAGE	NOTES
15959 Union Chapel Rd LLC / MD Co	Saglimbeni Properties LLC / MD Co	28 Feb. 2006	MDR 9852-644	Deed – fee simple	\$750,000	1) 3.8236 A 2) .3058 A	
Daisy Enterprises Ltd Partnership / ?	15959 Union Chapel Rd LLC / ?	4 June 2004	MDR 8456-158	Deed – fee simple	\$499,000	1) 3.8236 A 2) .3058 A	
Mullinex Motors, Inc.	Joan R. Mullinex G. Thomas Mullinex, co- partners of Daisy Enterprises Ltd. Partner.	11 Aug. 1988	1932-396				
A. Robey & Mildred M. Mullinex	Mullinex Motors, Inc.	14 June 1966	WHH 456-59	Deed – fee simple	\$5.00	1) 4.7565 A 821 A 2) ? 3) ?	
Norman & Pauline H. Mullinex (H/W) / Howard	A. Robey & Mildred M. Mullinex (H/W) / Howard	7 June 1944	BM Jr. 183-103	Deed – fee simple	\$5.00	4.7565 A	
Emma I. Ward, widow / Howard	Norman & Pauline H. Mullinex (H/W) / Howard	3 June 1929	HSK 136-288	Deed – fee simple	\$5.00	5-0-10 ARP 306 A	
George W. & Susan F. Ward (H/W) / Balto. City	Emma I. Ward	30 Jan. 1907	WWLC 84-126	Deed – fee simple	\$1,250	5-0-10 ARP	p/o "Ridgely's Great Park"
Sarah C. & John W. Ward (W&H) / Howard	George W. Ward	18 June 1900	JHO 72-320	Deed – fee simple	\$1,500	5-0-10 ARP	
Henrietta & Zadok Talbert (W&H) / Howard	Sarah C. Ward / ?	5 July 1880	LJW 42-402	Deed – fee simple	\$202.50	5-0-10 ARP	


THE WARD-MULLIN PROPERTY (HO-1035) 15959 UNION CHAPEL ROAD

CHAIN OF TITLE

GRANTOR/HOME	GRANTEE/HOME	DATE	· LIBER/ FOLIO	INSTRU- MENT	CONSIDER- ATION	ACREAGE	NOTES
William H. Gaither & wf Susan F. / Howard	Henrietta Talbert / Howard	28 Dec. 1876	LJW 37-382	Deed –	\$2,200	143 ¾ A	p/o "Ridgelys Range" p/o "Ridgelys Great Park" where Bunker Hill Road crosses Union Chapel Rd to W. side of Cattail River subject to mortgage money due Edwin W. Owings which Talbert & husb. Zadok agree to pay [no prev. ref.]
Charles Perry Gaither / Tallahasse, FL	William H. Gaither	23 Aug. 1870	31-32	Deed – fee simple	\$1.00 & property in deed of even date	1) 143 ¾ A 2) 20 A	p/o RE of late Perry Gaither "Ridgelys Great Park" 1) bounded by lands of Washington A. Peddicord, Evan T. Ridgely & late Caleb Dorsey [WWW 30-382, 75A of Perry Gaither's land to C.P.G.]

HO-1035 Ward-Mullinex Property 15959 Union Chapel Road, Daisy





HO-1035 Ward-Mullinex Property 15959 Union Chapel Road Woodbine quad

HO-1035 Ward-Mullinex Property 15959 Union Chapel Road Howard County, Maryland Ken Short, photographer

Photo Log
Nikon D-70 camera
HP Premium Plus paper
HP Gray Photo print cartridge

HO-1035_2011-02-07_01 North & west elevations

HO-1035_2011-02-07_02 Interior, ceiling



40-1035 Ward-Mullinex Property 15959 Union Chapel Road Howard County, Maryland Ken Short 2011-02-07 MD SHPO North & west elevations 10/2





HO-1035 Ward-Mulinex Property 15959 Union Chapel Road Howard County, Maryland Ken Short 2011-02-07 MD SHPO Interior, ceiling 20f2

